

Index

A

acceptable range(s) 2-1, 7 to 10; 6-5, 6, 8; 7-3; 8-1; 9-2; 10-3; 11-1; 12-1; 13-1; 14-1; 15-1
action lines 1-8
action zone 3-6, 7
adjusting process to aim 1-9, 25; 2-6; 6-5, 6
aeration 4-10
 bleach 12-1
 fixer 13-1
aerial oxidation 4-1
agitation 1-2, 24; 2-11; 4-1 to 3, 10 to 11; 7-3; 8-1; 10-3; 12-1; 13-1; 16-2
 air 4-10; 8-1; 12-1; 13-1; 14-1
 humidified nitrogen 4-2, 11
 nitrogen 4-11; 7-3; 10-3
aims 1-3 to 4, 9; 2-1, 5 to 10; 5-2 to 6; 6-1 to 3, 5 to 10; 7-3; 8-1; 9-2; 10-3; 11-1; 12-1; 13-1; 14-1; 15-1
 audit-strip 3-2 to 6
Appendix 4A 4-15
Appendix 4B 4-17
Audit Strips, Process E-6, KODAK
 3-1 to 7; 5-1, 2 to 5

B

bleach Section 12; 16-2
aeration 4-10; 12-1
agitation 4-10; 12-1
components 12-1
concentration 12-1
function 12-1
household 16-4
hydrometers for 4-3
preparing a fresh tank solution 12-1
recirculation 4-10
replenishment rate 12-1
specifications 12-1
specific gravity 12-1
temperature 12-1
time 12-1
blue color balance 2-8; 4-11; 6-8, 9, 9-1
bromide concentration 1-2, 24; 2-11; 3-2; 4-11, 13; 6-4; 7-1, 3, 4, 14 to 16, 17
 tables 7-5, 6
Bromide Test Kit, Process E-6, KODAK
 3-2; 4-11; 7-1, 4

C

carryover, developer 8-1
Checklists Section 17; 16-1
chemicals 1-2, 24; 4-6
 components 7-1; 9-1; 10-1, 2; 11-1; 12-1; 13-1; 15-1
 functions 7-1; 9-1; 10-1; 11-1; 12-1; 13-1; 15-1
 mixing 7-3; 9-2; 10-3; 16-3
cleaning
 rack-and-tank processors 16-4
 roller-transport processors 16-4
 solution tanks 16-4
Cleanup film 4955, KODAK Roller-Transport 16-4
color balance 1-11, 12, 15, 16; 2-8; 3-3, 4, 7; 5-7, 10; 6-5, 6; 10-2
 adjusting 2-8; 6-8 to 9
color couplers 7-1; 10-1
color developer Section 10; 1-16
 18, 20, 22, 24; 2-7; 6-7 8, 9, 10; 16-2
 agitation 2-11; 10-3
 components 10-1, 2
 concentration 2-7; 6-8; 10-3
 cycling 10-14
 diagnostic charts 10-5 to 13
 functions 10-1
 hydrometers for 4-3; 6-4
 oxidation 10-2
 pH adjustment 6-8 to 10
 preparing a fresh tank solution 10-3
 replenisher 2-8; 10-3
 replenishment rate 2-11; 10-3, 14
 14
 sensitometric effects of
 solution component
 concentration 10-2
 specifications 10-3
 specific gravity 2-11; 10-3, 14
 starter 10-3
sulfite concentration 1-2, 24; 2-11; 3-2; 4-11, 13; 6-4; 10-1, 3, 4, 10, 12, 14
temperature 2-11; 10-3, 14
time 10-3

Color Developing Agent CD-3, KODAK
 10-1, 2

color zones

 on plotting forms 4-13; 5-9

 on status reports 3-5, 6

compensating for evaporation
(Appendix 4A) 4-15

components, solution 1-24; 7-1, 2; 9-1;
 10-1, 2; 11-1; 12-1; 13-1; 15-1

concentration 1-24; 7-1, 2

 bleach 12-1

 bromide 1-2, 24; 3-2; 4-11, 13; 6-4;
 7-3, 4, 5, 6

 color developer 2-7; 6-7, 8, 9, 10;
 10-2, 3

 first developer 1-6, 18; 6-5; 7-1 to 3

 fixer 13-1

 pre-bleach 11-1

 reversal agent 1-2, 24; 3-2; 4-11, 13;
 6-3, 4; 9-1, 2, 3 to 4, 9, 10, 11, 12

 reversal bath 3-2; 4-13; 9-2

 sulfite 1-2, 24; 2-11; 3-2; 4-11, 13;
 6-4; 10-1, 3, 4, 10, 12, 14

contamination 16-3, 4

contrast 1-11, 16, 24; 6-7, 8, 10; 10-1, 2
 adjusting 2-7; 6-7, 8

 mismatch 3-4, 7

continuous processors 4-15; 16-4

control limits 1-3

Control Strips, Process E-6, KODAK

 1-1, 2, 11, 16, 18; 3-2, 4, 5; 4-1; 5-1 to 5-7

 calculating/plotting LD spread 5-8

 correction factors 5-2, 3, 6

 establishing aims 5-2 to 6

 plotting on form Y-33 3-2; 5-7 to 8
 reference strip 5-1, 2, 3, 6

control zone 3-5, 6, 7

countercurrent wash 14-1

critical zone 3-5, 6, 7

cycling 1-5, 7, 8

 color developer 10-14

 first developer 7-17

 reversal bath 9-12

KODAK Q-LAB Process Monitoring Service

PROCESS CONTROL HANDBOOK • Z-6

D

daily checklist Section 17; 16-1
defoamer 4-11
densitometer 3-5; 5-1, 2, 3, 6
Densitometer Check Plaque, KODAK
Transmission 5-1
Densitometer Correlation Strip,
Process E-6, KODAK 3-2, 5; 5-2, 3
density 1-12 to 15; 2-1 to 3, 7, 8;
6-7 to 9; 7-7
D-max 1-16; 3-3, 6, 8; 5-1, 2, 7, 9;
7-2, 7
D-min 3-3, 6; 5-1, 2, 7, 9, 10
high (HD) 1-16; 3-3, 4, 6, 7, 8;
5-1, 2, 7, 9; 6-7
LD spread 3-5, 6, 8; 5-5, 6, 7, 8, 9
low (LD) 1-16; 3-3, 4, 5, 6, 7, 8;
5-1, 2, 7, 8, 9, 10 to 13; 6-7, 10
toe (TD) 3-3, 4, 6, 7, 8; 5-1, 2, 5, 6, 7, 9,
10 to 13; 7-1
developing agents 7-1, 2; 10-1, 2
diagnostic charts
color developer 10-5 to 13
first developer 7-8 to 16
reversal bath 9-5 to 11
DIMEZONE S Developing Agent,
KODAK 7-1, 2
dirt 16-3
dryer 16-1, 4
drying 15-1
dye stability 11-1; 14-1
D-max 1-16; 3-3, 6, 8; 5-1, 2, 7, 9, 10; 7-2, 7
D-min 3-3, 6; 5-1, 2, 7, 9

E

EKTACHROME Films 1-12, 15; 3-1, 2; 5-1
evaporation 1-7, 18, 24; 4-1, 2, 3, 8, 11, 12;
6-4, 5; 7-1, 17; 10-14; 16-3, 4

F

film
speed 6-7
tracking 1-10 to 15
uniformity 1-24
filters
densitometer 5-1
solution 16-2, 3, 4
filtration 1-16
final rinse Section 15; 16-2
components 15-1
function 15-1
preparing a fresh tank solution 15-1
replenishment rate 15-1
specifications 15-1
time 15-1
final wash Section 14; 16-2
agitation 14-1
flow rate 14-1
function 14-1
specifications 14-1
temperature 14-1
time 14-1

first developer Section 7; 1-3, 5 to 7,
16, 18, 19, 21; 8-1; 16-2, 3
agitation 1-24; 4-2, 10; 7-3
bromide concentration 1-2, 24;
2-11; 3-2; 4-11, 13; 6-4; 7-1, 3,
4, 5, 6, 14 to 16, 17
concentration 1-3, 5 to 7; 7-3
components 7-1, 2
cycling 7-17
diagnostic charts 7-8 to 16
functions 7-1
hydrometers for 4-3
preparing a fresh tank solution
7-3
replenisher 1-6, 7; 7-1, 3
replenishment rate 1-7, 18; 7-3,
7, 12, 13, 17
sensitometric effects of solution
component concentration 7-2
specifications 7-3
specific gravity 1-5 to 7, 12, 13,
14, 15; 6-5; 7-3, 4, 9, 10, 17
starter 1-16; 7-3
tank turnovers 4-12
temperature 1-13, 14, 15; 2-1 to
3, 5, 7, 8, 9, 11; 4-10; 6-7, 9,
10; 7-3, 8, 17
time 1-24; 4-10; 6-7; 7-3, 11, 17
first wash Section 8; 6-8; 16-2
agitation 4-10; 8-1
flow rate 8-1
functions 8-1
specifications 8-1
temperature 2-11; 8-1
time 8-1
fixer Section 13; 16-2, 3, 4
aeration 13-1
agitation 13-1
components 13-1
concentration 13-1
function 13-1
hydrometers for 4-3
preparing a fresh tank solution
13-1
recirculation 4-10
replenishment rate 13-1
specifications 13-1
specific gravity 13-1
sulfurization 13-1
temperature 13-1
time 13-1
flowmeters 16-3
foaming 4-1, 11
form, plotting
Y-33 3-2; 5-5, 6, 7, 8, 9; 7-3; 9-2;
10-3
Y-34 3-2; 4-6, 8, 10, 13; 5-9;
6-6; 7-3, 4
Y-35 3-2; 4-6, 8, 10, 13; 5-9;
6-6; 9-2, 3
Y-36 3-2; 4-6, 8, 10, 13; 5-9;
6-6; 10-3, 4
frequency of measurements 4-12

G

green color balance 4-11; 9-1

H

handling
control strips 5-1, 9
photographic chemicals 4-14
household bleach 16-4
hydrometer crossover procedure
(Appendix 4B) 4-17
hydrometers, standard 4-3 to 4
Hydrometer Syphon Set, KODAK Process
4-3, 5, 6

I

in-line dilution 1-16; 4-8, 9; 6-5, 8; 16-3;
Worksheet 2
iron 11-1; 12-1; 13-1

K

KODAK Audit Strips, Process E-6
3-2 to 4; 5-1, 2 to 5
KODAK Bromide Test Kit, Process E-6
3-2; 4-11; 7-1, 4
KODAK Control Strips, Process E-6
1-1, 2, 11, 10, 16, 18; 3-2, 4, 5; 4-1; 5-1 to 2
KODAK Process Hydrometer Syphon Set
4-3, 5, 6
KODAK Q-LAB Chemical Test Kit,
Process E-6 3-2
KODAK Q-LAB Densitometer Correlation
Strip, Process E-6 3-2, 5; 5-2, 3
KODAK Q-LAB Process Monitoring
Service Section 3; 1-1
KODAK Reversal Agent Test Kit,
Process E-6 3-2; 4-11; 9-1, 3
KODAK Sulfite Test Kit, Process E-6
3-2; 4-11; 10-1, 4
KODAK Transmission Densitometer
Check Plaque 5-1

L

LD (low density) 1-16; 3-3, 4, 5, 6, 7, 8;
5-1, 2, 7, 9, 10 to 12; 6-7, 8, 10
LD spread 3-5, 6; 5-5, 6, 7, 8, 9
level shift 1-5, 6
low utilization 1-24; 4-1, 12; 6-4

KODAK Q-LAB Process Monitoring Service

PROCESS CONTROL HANDBOOK • Z-6

M

magenta color balance 3-7; 10-2
maintenance Section 16
 bimonthly 16-3
 biweekly 16-3
 daily 16-3
 frequency chart 16-2
 monthly 16-3
 weekly 16-3
maximum density 3-3; 5-1, 2, 9
measurements, frequency of 4-12
minimum density 3-3; 5-1, 2, 9
mixing, chemical 7-3; 9-2; 10-3; 16-3
monitoring, process Section 4; Section 5;
 1-24; 2-11
 chemical parameters 1-24; 2-11; 4-3
 frequency chart 16-2
 mechanical parameters 1-24; 2-11;
 4-3
 sensitometric parameters 5-1 to 12
monitoring toe density 5-10 to 13

N

nitrogen agitation 4-2, 11; 7-3; 10-3
nonuniformity 4-10

O

optimizing your process 6-7 to 10
orange zone 3-5, 6, 7; 4-13; 5-9
outliers 1-5, 6
overreplenishment 4-3
oxidation 1-24; 4-1, 2, 12; 7-1; 16-3

P

parameters, key process Section 4;
 1-2, 16, 18, 24; 2-11; 4-1
 agitation 2-11; 4-1, 2, 3, 10, 11
 bromide concentration 1-2, 24; 2-11;
 3-2; 4-11, 13; 6-4; 7-1, 3, 4, 14 to 16
 chemical 1-2, 12, 16, 24; 2-11;
 4-1, 4, 13
 mechanical 1-2, 12, 16, 24; 2-11;
 4-1, 4, 13
 recirculation 2-11; 4-3, 10
 reversal-agent concentration 1-2, 24;
 2-11; 4-11, 13; 9-1, 2, 3 to 4, 9, 10, 11,
 12
 specific gravity 1-2, 3, 12, 13, 14,
 15, 18, 24; 2-11; 4-3 to 6, 13
 sulfite concentration 1-2, 24; 2-11;
 3-2; 4-11, 13; 6-4; 10-1, 3, 4, 10,
 12
 temperature 1-24; 2-11; 4-3, 10, 13
 time 1-24; 2-11; 4-3, 10, 13
 replenishment rates 1-24; 2-11; 4-3,
 6 to 9, 13; Worksheet 1; Worksheet 2
parameters, sensitometric Section 5
pH adjustment, in color developer 6-8 to 10

plotting forms

Y-33 3-2; 5-5, 6, 7, 8, 9; 7-3;
 9-2; 10-3
Y-34 3-2; 4-6, 8, 10, 13; 5-9;
 6-6; 7-3, 4
Y-35 3-2; 4-6, 8, 10, 13; 5-9;
 6-6; 9-2, 3
Y-36 3-2; 4-6, 8, 10, 13; 5-9;
 6-6; 10-3, 4
pre-bleach Section 11; 16-2, 3
carryover (into bleach) 12-1
concentration 11-1
functions 11-1
hydrometers for 4-3
preparing a fresh tank
 solution 11-1
replenishment rate 11-1
specifications 11-1
temperature 11-1
time 11-1

process

control Section 1; 4-1, 10, 12
monitoring Section 4; Section 5
monitoring and maintenance
 frequency chart 16-2
record form 5-1, 7

processing solutions Sections 7, 9,
 10, 11, 12, 13, 15

processors

 continuous 4-11; 16-4
 rack-and-tank 4-1, 11; 16-4
 roller-transport 4-10; 16-4

Process Record Form, KODAK 5-1,
 7

Publications, KODAK

 No. J-98A 4-14
 No. J-411 4-14

 No. Y-33 3-2; 5-5, 6, 7, 8; 7-3
 9-2; 10-3

 No. Y-34 3-2; 4-6, 8, 10, 13;
 5-9; 6-6; 7-3, 4

 No. Y-35 3-2; 4-6, 8, 10, 13;
 5-9; 6-6; 9-2, 3

 No. Y-36 3-2; 4-6, 8, 10, 13;
 5-9; 6-6, 10-3, 4

 No. Y-55 5-1, 7

 No. Z-119 5-12; 12-1

push processing, replenishment for
 7-7

Q

Q-LAB Chemical Test Kit, Process E-6 3-2
Q-LAB Densitometer Correlation Strip,
 Process E-6 3-2; 5-2, 3
Q-LAB Process Monitoring Service
 Section 3; 1-1

R

rack-and-tank processors 4-1, 11; 7-3; 8-1;
 10-3; 14-1; 16-3, 4
racks, cleaning 16-4
recirculation 4-3, 10; 16-3
red color balance 12-1
red zone 3-5, 7
reference strip 5-1, 2, 3, 6
Regional Quality Centers 3-1, 2, 5
replenisher concentration 1-24
replenishment

 calculating rates 4-6 to 9; Worksheet 1;
 Worksheet 2

systems (maintenance for) 16-3

reversal agent 1-2, 24; 3-2; 4-11; 9-1, 2,
 3 to 4, 9, 10

Reversal Agent Test Kit, Process E-6,
 KODAK 3-2; 4-11; 9-1, 3

reversal bath Section 9; 4-11, 13; 8-1; 16-2
 components 9-1

 concentration 4-2; 9-2, 3, 12

 cycling 9-12

 diagnostic charts 9-5 to 11

 function 9-2

 hydrometers for 4-3

 preparing a fresh tank solution 9-2

 replenisher 9-2

 replenishment rate 9-2, 12

 reversal agent 1-2, 24; 3-2; 4-11; 9-1

 reversal-agent concentration 9-1, 2,
 3 to 4, 9, 10, 12

 reversal-bath uniformity 9-3

 sensitometric effects of reversal-agent
 concentration 9-1

 specifications 9-2

 specific gravity 9-2, 12

 temperature 9-2

 time 9-2

 replenishment, monitoring rates 1-2, 3, 24;
 2-11; 4-1, 3, 6 to 9, 11; 6-4

rollers 4-10; 6-4; 16-3, 4

roller-transport processors 4-10; 16-3, 4

Roller-Transport Cleanup Film 4955,
 KODAK 16-4

KODAK Q-LAB Process Monitoring Service

PROCESS CONTROL HANDBOOK • Z-6

S

sheet film 4-11; 7-7
shutdown 16-3
silver 7-7
 bromide 7-1; 12-1; 13-1
 halide 7-1; 9-1; 10-1, 2; 11-1; 13-1
 image 7-1
 metallic 7-1; 10-1; 11-1; 12-1
 nitrate solution 7-4
sodium hydroxide 1-1, 16, 18; 2-8, 9;
 6-8, 9, 10
specific gravity 1-2, 3, 5 to 7, 12 to 15, 18;
 2-7 to 9; 4-1, 2, 3 to 6; 6-4 to 6, 8, 9, 10;
 7-3, 4; 9-2; 10-3
 acceptable range 2-7, 11; 10-3
 measuring 4-3 to 6; 16-3
 monitoring 1-24; 2-11
 plotting 4-6
squeegees 16-4
starter
 color developer 10-3
 first developer 1-16; 7-3
status reports 3-1, 2, 5 to 8
 sample reports 3A to 3K
sulfite concentration 1-2, 24; 2-11; 3-2;
 4-11, 13; 6-4; 10-1, 3, 4, 10, 12, 13
Sulfite Test Kit, Process E-6, KODAK
 3-2; 4-11; 10-1, 4
sulfuric acid 6-8

T

tank cleaning 16-4
tank turnovers 4-12
tanks, processing 4-1, 2
temperature 1-2, 3, 24; 16-2
 acceptable range 2-7
 first wash 2-11; 8-1
 monitoring 2-11; 4-10
 plotting 1-3; 4-10
 tolerance(s) 2-2, 3, 5
time 1-2, 3, 24; 16-2, 3
 monitoring 2-11; 4-10; 6-4
 plotting 1-3; 4-10
titration 7-4; 10-4
tolerances 2-1 to 6, 8; 6-1 to 3,
 5 to 6, 7, 9, 10
turbulator bars 4-11
turbulence 4-2

U

underreplenishment 4-3
uniformity 4-10
utilization, processor 1-24; 4-12; 6-4

W

wash
 final Section 14; 2-11; 16-2
 first Section 8; 2-11; 4-15; 6-4, 8; 16-2
 flow rate 8-1; 14-1
 tanks, draining and cleaning 16-4
 temperature 8-1; 14-1; 16-2
water conservation 8-1; 14-1
white zone 3-5; 4-13; 5-9; 6-6

Y

Y-33 Form 3-2; 5-5, 6, 7, 8, 9; 7-3; 9-2; 10-3
Y-34 Form 3-2; 4-6, 8, 10, 13; 5-9; 6-6;
 7-3, 4
Y-35 Form 3-2; 4-6, 8, 10, 13; 5-9; 6-6;
 9-2, 3
Y-36 Form 3-2; 4-6, 8, 10, 13; 5-9; 6-6;
 10-3, 4
Y-55 Form 5-1, 7
yellow color balance 4-11; 6-8; 9-1; 10-2
yellow zone 3-5, 7; 4-13; 5-9; 6-6

Z

Z-119, KODAK Publication No. 5-12; 12-1